

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,901,754 B2
DATED : June 7, 2005
INVENTOR(S) : Mark J. Jervis

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 8.

- Line 4, after "load-sense" insert -- line --.
- Line 27, change "a supply" to -- the supply --.
- Line 39, change "a bypass compensator" to -- a second bypass compensator --.
- Line 40, delete "second".
- Line 45, change "second" to -- first --.
- Line 54, change "first" to -- second --.

Signed and Sealed this

Twenty-seventh Day of September, 2005



JON W. DUDAS
Director of the United States Patent and Trademark Office